

Job Number: 247837 / GR10882 0CFEC5F72045

Job Date: 29/08/24

Driver: SCDAVE

Mileage: 48439

Email:

Account No: AAEB5

Location: DUISBURG WAY ON R/S NEXT TO SOUTHSEA COMMON PORTSMOUTH, SOUTHSEA, ENGLAND, PO5 3JF, PIER ...

Destination: BOARHUNT GARAGE LIMITED, UNIT A/A1 FORT WALLINGTON FAREHAM , HAMPSHIRE , PO16 8TT 1A

VRM / VIN: BF71EWG / ZCFCG35A405443386

Fleet Number:

Vehicle Iveco Daily 35S14b / WHITE

Symptom: RECOVERY:WONT START:

Fault Found: Clutch

Outcome: Tow to contractor base for redelivery

**Boarhunt Garage
and Recovery
Services Ltd
Recovery Report**

Printed: 15/01/25

Vehicle Condition Report

Weather / Vehicle Condition

Vehicle

☐ Clean ☐ Wet

☒ Dirty ☒ Unable to see fully

Weather

☐ Raining ☐ Snowing ☐ Fog

Time of Day

☐ Day ☒ Night

Type of Lift

☒ Total Lift ☐ Front Lift

☐ Rear Lift ☐ Straight Bar

☐ Propshaft Removed ☐ LLC

☐ Halfshaft Removed ☐ Damaged Wheels

☐ Brakes Released ☐ Missing Wheels

Items Present

☒ Keys ☐ Dashcam

☐ Phone / electronic ☐ Money

☐ Child Seat ☐ Purse / Wallet

☐ Credit Cards

Damage



☒ Broken
☒ Damaged
☐ N/A

Acceptance Statements

☐ Unattended Delivery Authority
☐ Acceptance that a visual vehicle inspection was not practical on arrival.

Customer Acceptance

Name: DOHERTY MR BRIAN

Date: 29/08/24 23:16

Customer Unable / Refused to Sign

Delivery Condition Report

Customer accepted delivery in the same condition as recovery

Name: Doherty

Date: 29/08/24

Customer Unable / Refused to Sign